


## TC-400-NM-RP (stock code: 3190-960)


Type N-Male Plug (Reverse Polarity)  
solder-on center contact  
crimp-on (.429" hex.) outer contact

### INSTALLATION INSTRUCTIONS


(Cable Types: LMR-400; 400 DB; 400 FR; 400 Ultraflex; 400 LLPL)



- (A) Trim cable to dimensions shown using a razor knife or Times ST-400C strip tool.  
(B) Remove any residual plastic from center conductor.  
(C) Deburr center conductor using a fine file or Times DBT-01 tool.



- (A) Slide weather seal and crimp ferrule over cable.  
(B) Seat center contact firmly against cable dielectric and solder cable to conductor. Use minimal heat to minimize melting of foam dielectric. Inspect to be sure aluminum foil is not touching center contact.



- (A) Flare braid and insert cable into connector body until dielectric is seated with all braid wires on outside of connector body and aluminum tape inside connector body.  
(B) Trim excess braid flush to shoulder on connector.  
(C) Slide crimp ring over braid and crimp as close to body as possible using a .429 hex. die in a Times HX-4 crimp tool or equivalent. Do not crimp rear of crimp sleeve.  
(D) Heat shrink weather seal over rear of connector body and down on to cable jacket using hot air gun.